

# TPC readout board studies R. D. BN

---

- For old and new T1 as well as MTPC2 sparks are mainly located on the HV bus.
  - T2 is operational.
  - With the old T1 we learned that “painting” with a good insulator is a good solution.
  - But the substrate has to be cleaned before.
  - A two component epoxy would be the best solution. Can be repaired.
-

## TPC cont.

---

- MTPC2 sparks from solder pad to bus.
  - Same solution as T1.
  - Once HV bus problems are fixed new weaknesses may appear between wires.
  - We have to clean these TPCs
-